

Buffer Under-run Protection

A buffer under run occurs during recording if the recorder runs out of data in the recording buffer. The laser is indeed able to stop writing for any amount of time and resume when the buffer is full again.